


- FOUND LEAD, TACK & TAG "LS 4016" PER P.W.F.B. 1718-304. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH.
- FOUND LEAD, TACK & TAG "LS 4016" PER P.W.F.B. 1718-302. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH, SET BY TIES PER P.W.F.B. 1718-302.
- ▲ FOUND CONC. NAIL, IN LIEU OF LEAD & TACK PER C.E.F.B. 171-177/114. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH, SET BY TIES PER C.E.F.B. 171-177 PG 114.
- ⊙ FOUND TIE PER P.W.F.B. 1718-304.
- ⊙ FOUND TIE PER P.W.F.B. 1718-302.
- ⊙ FOUND TIE AS NOTED, PER C.E.F.B. 171-177 PG 114.
- ⊙ FOUND TIE AS NOTED.
- ( ) INDICATES RECORD DATA PER P.W.F.B. 1718-302.
- [ ] INDICATES RECORD DATA PER C.E.F.B. 171-177/114.
- ⊕ INDICATES TRANSIT TIE.



THE PURPOSE OF THE RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771. NO CLAIM IS MADE AS TO THE CORRECTNESS OF THE POSITION(S) OF SAID MONUMENT(S), NOR THE DIMENSIONAL RELATIONSHIP TO STREET CENTERLINES OR PROPERTY BOUNDARIES

THOMAS GUIDE PG 563/B3

FB 338 P. 324

# CORNER RECORD

PWFB 1718

1409


City of BURBANK

Document Number \_\_\_\_\_

County of LOS ANGELES

California

Brief Legal Description INTERSECTIONS OF CLARK STREET (SEE NOTE BELOW)



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other

Date of Survey MARCH 26, 2012

### COORDINATES(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Vert. Datum: NGVD29  NAV88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

**NOTE: INTERSECTIONS OF CLARK STREET & KEMP STREET / ARCOLA AVENUE, CLARK STREET & FORD STREET / PALCIDIA AVENUE, CLARK STREET & LEDGE AVENUE.**

**LOCATED EXISTING SURVEY MONUMENT PRIOR TO CONSTRUCTION  
TIED OUT AND RESET AFTER CONSTRUCTION.**

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2 OF 2

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on OCTOBER 8, 2012.

Signed John E. Lieser P.L.S. or R.C.E. Number 3983



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 08 2012 OCT 29 2012 and examined and filed NOV 26 2012.

Signed Curt M. O'Bryan P.L.S. or R.C.E. Number 6388

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_

