


- FOUND 1" IP WITH TAG "LS 4016" PER P.W.F.B. 1718-310. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH, SET BY TIES PER P.W.F.B. 1718-310.
- FOUND LEAD & TACK PER P.W.F.B. 1718-306. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH.
- ▲ FOUND SPIKE W/ WASHER "LS 4016" PER P.W.F.B. 1718-320. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH, SET BY TIES PER P.W.F.B. 1718-320.
- FOUND SPIKE W/ WASHER ILLEGIBLE, NO REF. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH.
- ⊙ FOUND LEAD & TACK PER P.W.F.B. 1718-320.
- ▲ FOUND SPIKE PER P.W.F.B. 1718-320.
- FOUND LEAD AND RIVET PER P.W.F.B. 1718-310 OR PER P.W.F.B. 1718-306.
- ⊙ SET LEAD, TACK & TAG "LS 3983" FOR TRANSIT TIE.
- () INDICATES RECORD DATA PER P.W.F.B. 1718-310.
- [] INDICATES RECORD DATA PER P.W.F.B. 1718-306.
- { } INDICATES RECORD DATA PER P.W.F.B. 1718-320.
- ⊕ INDICATES TRANSIT TIE.



THOMAS GUIDE PG 563/C3

THE PURPOSE OF THE RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771. NO CLAIM IS MADE AS TO THE CORRECTNESS OF THE POSITION(S) OF SAID MONUMENT(S), NOR THE DIMENSIONAL RELATIONSHIP TO STREET CENTERLINES OR PROPERTY BOUNDARIES

CORNER RECORD

PWFB 1718


PB 338 P. 326
1411

City of BURBANK

Document Number _____

County of LOS ANGELES, California

Brief Legal Description INTERSECTIONS OF CLARK AVENUE (SEE NOTE BELOW)



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAV88
 Meas. Units: Metric Imperial

Date of Survey MARCH 26, 2012

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.

NOTE: INTERSECTIONS OF CLARK AVENUE & VALLEY STREET, CLARK AVENUE & CLYBOURN AVENUE, CLARK AVENUE & SANCOLA AVENUE. ALSO INCLUDING A MONUMENT ON CLARK AVENUE 340'± WLY OF SANCOLA AVENUE. LOCATED EXISTING SURVEY MONUMENT PRIOR TO CONSTRUCTION TIED OUT AND RESET AFTER CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2 OF 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 29, 2012.

Signed John E. Lieser P.L.S. or R.C.E. Number 3983



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 08 2012 and examined OCT 29 2012 and filed NOV 26 2012

Signed Curt M. O'Bryan P.L.S. or R.C.E. Number 6388

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

