


FB338 P. 261



FD L/T IN T.C.
PER CALTRANS FB
A22.003-45
CURB REMOVED
DURING CONSTRUCT.
RESET L/TAG
'PLS7892' RECESSED
IN SAME LOCATION
AFTER CONSTRUCT.

FD L/T IN GUTTER
PER CALTRANS FB
A22.003-45

FD L/T IN T.C.
PER CALTRANS FB
A22.003-45

FD SPK/W IN A/C PVMT PER
CALTRANS FB A22.003-45
PAVEMENT REMOVED DURING
CONSTRUCT FOR NEW CONC SURFACE.
RESET L/TAG 'PLS7892' RECESSED
IN SAME LOCATION AFTER CONSTRUCT.

SET L/TAG
'PLS7892'
RECESSED IN
CONC SWALE

FD L/T IN T.C.
PER CALTRANS FB
A22.003-45

FD L/T IN
GUTTER
PER CALTRANS
FB
A22.003-45

FD SPK/W IN A/C PVMT PER
CALTRANS FB A22.003-45
PAVEMENT REMOVED DURING
CONSTRUCT FOR NEW A/C PVMT.
RESET W/P.K. SPK/WASHER
'LS7892' RECESSED IN SAME
LOCATION AFTER CONSTRUCT.

VARNEY ST

ELM CT

T.C. = TOP OF CURB


CORNER RECORD

Document Number _____

City of BURBANK

County of Los Angeles, California

Brief Legal Description ELM CT & WARNEY ST.



CORNERTYPE

Govt. Corner Control
 Meander Property
 Rancho Other
 Date of Survey 1-02-12

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found & tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PLAT

A description of the physical condition of the monument as found and as set or reset: _____


SEE PLAT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance

with the Land Surveyors' Act on FEB 10 2012

Signed [Signature] P.L.S. or R.C.E. No. 7892



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title: _____

County Surveyor's Comment _____