


# CORNER RECORD

Document Number \_\_\_\_\_

City of BURBANK County of Los Angeles, California

Brief Legal Description POST - CONSTRUCTION TIE OUT - TULARE AVE & LINCOLN AVE.



### CORNER TYPE

Govt Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey NOV. 2014 - APR. 2015

### COORDINATES (Optional)

N, \_\_\_\_\_  
 E, \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD29  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum NGVD29  NADV88   
 Meas. Units Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner

MONUMENTS AND TIES DESCRIBED AS SHOWN (SEE PLAT). NEW CENTER LINE TIES SHOWN  
 HEREON (SEE PLAT) ESTABLISHED AFTER PAVING CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
 ALL TIES SHOWN ARE FOR THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION.  
 NO CLAIM IS MADE AS TO THE RELATIONSHIP THE MONUMENTS, TIES OR LINES SHOWN  
 HEREON (SEE PLAT) TO THE TRUE BOUNDARY LOCATION.

### SURVEYORS STATEMENT

This Corner Record was prepared by me or under my direction in conformance  
 with the Land Surveyors Act on APRIL 23, \_\_\_\_\_ 2015

Signed [Signature] P.L.S. No. LS 2883



### COUNTY SURVEYORS STATEMENT

This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S. or R.C.E. No. \_\_\_\_\_

Title \_\_\_\_\_

County Surveyors Comment \_\_\_\_\_