


⊕ = TANGENT OVER

UNABLE TO VERIFY CENTERLINE POSITION



▲ FD PUNCHED DOME SPK & RUSTED WASHER NO REF., POSSIBLY P.I., DOWN 0.1', UNABLE TO VERIFY CENTERLINE POSITION BEFORE CONSTRUCTION. SET MAG. NAIL & W, STAMPED "LS 5411" PER TIES HEREON, FLUSH, AFTER CONSTRUCTION.

○ SET L, T & T "LS 5411" & CHISELED "T" IN T.C.

THE PURPOSE OF THIS RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771. NO CLAIM IS MADE REGARDING THE CORRECTNESS OF THE POSITION(S) OF SAID MONUMENT(S), NOR THE DIMENSIONAL RELATIONSHIP TO STREET CENTERLINES OR PROPERTY BOUNDARIES.

14-TRO-653

CORNER RECORD


PWFB 1819

1159

Document Number _____

City of BURBANK County of LOS ANGELES, California

Brief Legal Description STEPHEN ROAD; 100' ± SW'LY OF KENNETH ROAD



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 1/5/2015 & 2/16/2015

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish corner:
Found as described on the reverse of this sheet.

A description of the physical condition of the monument as found and as set or reset: _____
See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on 3/3/2015
 Signed [Signature] P.L.S. or R.C.E. No. L.S. 5411



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 25 2015
 examined and filed APR 16 2015
 Signed [Signature] P.L.S. or R.C.E. No. 6388
 Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____