

Fd. Lead and rivet in conc. walk per CEFB 181-34

Fd. Lead and rivet in conc. walk per CEFB 181-34

Fd. Lead and rivet in conc. walk per CEFB 181-34

Set spike and washer stamped LS 4016 by intersection of tie lines

Fd. Lead and rivet in conc. walk per CEFB 181-34


# CORNER RECORD

Document Number \_\_\_\_\_

City of BURBANK

County of Los Angeles, California

Brief Legal Description POST-CONST. MONUMENTATION (HEFFRON DR. & SCREENLAND DR.)



### CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey 3/22/99

### COORDINATES (Optional)

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PLAT

A description of the physical condition of the monument as found and as set or reset:

SEE PLAT

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on MARCH 27, 1999

Signed David L. Lindell P.L.S or R.C.E. No. LS 4016  
EXPIRES 6/30/00



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_  
and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S or R.C.E. No. \_\_\_\_\_

Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_