


FB-335 P. 285



N. T. S.



REFERENCE: CEFB 285-45 & COR. REC.
DISTANCES MEASURED HORIZONTAL

DATE: DECEMBER 29, 2003
SURVEYED BY: J. P. OSTLY
P.L.S. 5691


CORNER RECORD

Document Number _____

City of BURBANK

County of Los Angeles, California

Brief Legal Description P. I. ROSE ST. N/O TOLUCA PARK DR - C/L MONUMENT PRESERVATION



CORNERTYPE

Govt. Corner Control
 Meander Property
 Rancho Other
 Date of Survey 29-Dec-03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found & tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

see plat;

distances measured horizontal;


A description of the physical condition of the monument as found and as set or reset: _____

see plat;

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance
 with the Land Surveyors' Act on 29-Dec-03

Signed *John P. Ostly* PLS or R.C.E. No. 5691



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title: _____

County Surveyor's Comment _____