


FB-335 P. 359



REFERENCE: CEFB 285-45 & COR. REC.
 DISTANCES MEASURED HORIZONTAL

DATE: DECEMBER 29, 2003
 SURVEYED BY: J. P. OSTLY
 P.L.S. 5691

CORNER RECORD


Document Number

397

City of BURBANK

County of Los Angeles, California

Brief Legal Description P. I. ROSE ST. N/O TOLUCA PARK DR - C/L MONUMENT PRESERVATION



CORNERTYPE

Govt. Corner [] Control []
Meander [] Property []
Rancho [] Other [x]
Date of Survey 29-Dec-03

COORDINATES (Optional)

N.
E.
Zone NAD27 [] NAD83 []
NAD83 Epoch
Elev.
Vert. Datum: NGVD29 [] NAVD88 []
Meas. Units: Metric [] Imperial []

Corner - Left as found [] Found & tagged [] Established [] Reestablished [] Rebuilt []

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: see plat;

distances measured horizontal;

A description of the physical condition of the monument as found and as set or reset:

see plat;

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 29-Dec-03

Signed [Signature] P.L.S. or R.C.E. No. 5691



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 20 2004

and examined and filed FEB 04 2004

Signed [Signature] P.L.S. or R.C.E. No.

Title: DEPUTY COUNTY SURVEYOR

County Surveyor's Comment



5116 2-2-04