


FB 338 P. 283

- R-1 = COUNTY OF LOS ANGELES PWFB 1719/547-548
- [] = RECORD & MEASURED DISTANCE PER R-1
- () = RECORD DISTANCE PER R-1
- ⊕ = TANGENT OVER



- ▲ FD SPK/W UNREADABLE FLUSH PER R-1 BEFORE AND AFTER CONSTRUCTION.
- FD L/R & CHISELED T IN WALK PER R-1 BEFORE CONSTRUCTION. SET L/T "LS 5411" & CHISELED T FLUSH IN WALK AFTER CONSTRUCTION.
- FD L/R & CHISELED T IN WALK PER R-1.
- ◎ FD L/T "LS 4848" & CHISELED T FLUSH IN WALK PER R-1.

THE PURPOSE OF THIS RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771. NO CLAIM IS MADE REGARDING THE CORRECTNESS OF THE POSITION(S) OF SAID MONUMENT(S), NOR THE DIMENSIONAL RELATIONSHIP TO STREET CENTERLINES OR PROPERTY BOUNDARIES.


12-ALL-049

CORNER RECORD PWFB 1719

Document Number 1141

City of BURBANK County of LOS ANGELES, California

Brief Legal Description CLARK STREET & BEACHWOOD DRIVE



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/02/2012

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish corner:
Found as described on the reverse of this sheet.

A description of the physical condition of the monument as found and as set or reset:
See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on 9/17/2012

Signed [Signature] P.L.S. or R.C.E. No. LS. 5411




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEP 19 2012

examined and filed OCT 09 2012

Signed [Signature] P.L.S. or R.C.E. No. 6388

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____