

- FOUND SHAFT SPIKE NO REF. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH.
- ▲ FOUND 1" IP NO TAG, NO REF. DESTROYED DUE TO CONSTRUCTION. SET MAG. NAIL W/ BRASS WASHER "LS 3983" FLUSH.
- SET LEAD, TACK AND TAG "LS 3983" FOR TRANSIT TIE.

THOMAS GUIDE PG 534/B6

THE PURPOSE OF THE RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771. NO CLAIM IS MADE AS TO THE CORRECTNESS OF THE POSITION(S) OF SAID MONUMENT(S), NOR THE DIMENSIONAL RELATIONSHIP TO STREET CENTERLINES OR PROPERTY BOUNDARIES

FB 338 P. 308

CORNER RECORD

PWFB 1820


162

City of BURBANK

Document Number _____

County of LOS ANGELES, California

Brief Legal Description VIA CARMELITA 300'± WLY OF PASEO REDONDO



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey MARCH 26, 2012

COORDINATES(Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elevation _____

Vert. Datum: NGVD29 NAV88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

LOCATED EXISTING SURVEY MONUMENT PRIOR TO CONSTRUCTION
TIED OUT AND RESET AFTER CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset: _____


SEE SHEET 2 OF 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on OCTOBER 8, 2012

Signed John E. Lieser P.L.S. or R.C.E. Number 3983



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 08 2012 and examined OCT 29 2012

and filed NOV 26 2012

Signed Curt M. O'Bryan P.L.S. or R.C.E. Number 6388

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

