


CORNER RECORD

Document Number _____

City of BURBANK

County of LOS ANGELES, California

Brief Legal Description THE INTERSECTION OF LIMA STREET & AVON STREET



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey MARCH 26, 2012

COORDINATES(Optional)

N: _____
E: _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vert. Datum: NGVD29 NAV88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.

LOCATED EXISTING SURVEY MONUMENT PRIOR TO CONSTRUCTION
TIED OUT AND RESET AFTER CONSTRUCTION.


A description of the physical condition of the monument as found and as set or reset: _____

SEE SHEET 2 OF 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JUNE 29, 2012.

Signed _____ P.L.S. or R.C.E. Number 3983



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined
and filed _____.

Signed _____ P.L.S. or R.C.E. Number _____

Title _____

County Surveyor's Comment _____

