

FB 338 P.449

LEGEND

R1 = C.B.T.B. 322/419

▲ FD SPIKE & WASHER, 'CITY ENGR' WITH 4 STRADDLES, PER R1, PRIOR TO CONSTRUCTION. DESTROYED DUE TO CONSTRUCTION. SET SPIKE & WASHER 'RCE 27743' FLUSH AFTER CONSTRUCTION.

● FD LEAD, TACK & TAG 'CITY ENGR' AS INDICATED, PER R1

■ FD LEAD, TACK & TAG 'LS 5748' IN TC, NO REF


⊙ FD LEAD AND TACK HOLE IN SDWK, NO REF, PRIOR TO CONSTRUCTION. DESTROYED DUE TO CONSTRUCTION. SET LEAD, TACK & TAG 'RCE 27743' IN SDWK FLUSH AFTER CONSTRUCTION.

() DISTANCE PER R1

(()) MEAS. & DIST PER R1

R.C.C.

NOTE:
* TIE POINTS IDENTIFIED WITH A CHISELED 'T' BEHIND IT.




CORNER RECORD

PWFB 1719

1202

Document Number _____

City of BURBANK County of LOS ANGELES, CaliforniaBrief Legal Description VERDUGO AVENUE AND SIXTH STREET**CORNER TYPE**

Government corner Control
 Meander Property
 Rancho Other
 Date of Survey 12/18/13

COORDINATES (OPTIONAL)

N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FD MONUMENT, TIES AND TIED OUT PRIOR TO CONSTRUCTION, SET SPIKE AND WASHER AFTER CONSTRUCTION AS SHOWN ON SHEET 2 OF THIS RECORD.

A description of the physical condition of the monument as found and as set or reset: _____
SEE SHEET 2 OF THIS RECORD

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 01/17/14

Signed _____ P.L.S. or R.C.E. Number 27743

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received MAR 05 2014
 and examined and filed APR 17 2014

Signed Curt M. O'Bryan P.L.S. or R.C.E. Number 6388

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____