

SET L & TAG  
LS 4016 WITH  
CHIS'D "T"



9.75'

ROAD

Ø

42.67'

FD. L & TAG LS 5411 PER  
PWFB 1819-885/886  
(C.E.F.B. 338-387)

2.9'

48.95'

FIFTH

STREET

48.13'

FD. S&W LS 5411 PER  
PWFB 1819-885/886  
(C.E.F.B. 338-387)

15.7'

42.49'

FD. L & TAG LS 5411 PER  
PWFB 1819-885/886  
(C.E.F.B. 338-387)

DELAWARE

FD. L & TAG  
LS 5411 PER  
PWFB 1819-  
885/886 (C.E.F.B.  
338-387)


# CORNER RECORD

INDEX \_\_\_\_\_ PAGE \_\_\_\_\_

City of BURBANK

County of Los Angeles, California

Brief Legal Description: DELAWARE ROAD & FIFTH STREET



### CORNER TYPE

### COORDINATES (optional)

- Govt. Corner
- Meander
- Rancho
- Date of Survey: 7/7/15
- Control
- Property
- Other

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

- Corner —  Left as Found  Found & Tagged  Established  
 Reestablished  Rebuilt

**Identification & Type of Corner Found:** Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PLAT

A Description of the Physical Condition of the Monument as Found and as Set or Reset: \_\_\_\_\_

SEE PLAT

### Surveyor's Statement

This Corner Record was Prepared by Me or Under My Direction in Conformance with the Land Surveyors Act on JULY 8, 2015 19 \_\_\_\_.

Signed: \_\_\_\_\_

L.S. or R.C.E. No.: LS 4016



### County Surveyor's Statement

This Corner Record was Received \_\_\_\_\_ 19 \_\_\_\_ and Examined and Filed \_\_\_\_\_ 19 \_\_\_\_.

Signed: \_\_\_\_\_

Title: \_\_\_\_\_

County Surveyor's Comment: \_\_\_\_\_

T.G. 533-G-6