

CORNER RECORD


Document Number _____

City of BURBANK

County of Los Angeles, California

CENTERLINE INTERSECTION OF MAPLE STREET AND MAGNOLIA BLVD.

Brief Legal Description _____



CORNER TYPE

Govt. Corner Control
 Meander Property
 Rancho Other
 Date of Survey DEC. 16 2014

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found & tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

PERPETUATION OF THE CITY OF BURBANK SPIKE AND WASHER AT
THE CENTERLINE INTERSECTION OF MAPLE STREET AND MAGNOLIA BLVD. AS
PER CITY BURBANK FB 319-179 AND PWFB 1718-670,671

A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance

with the Land Surveyors' Act on DECEMBER 23 2014

Signed [Signature] P.L.S. or R.C.E. No. 5148



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title: _____

County Surveyor's Comment _____

